

Make a Filter

Working Diagram



NO	Assignment Order
1	Find the corresponding mold or iron cover according to customer requirements, and then find the iron mesh of the corresponding material and specification
2	Measure the diameter of the die and calculate the length of the iron mesh required
3	Set the length of the net cutting machine and the required quantity of the order according to the calculated value, and start cutting the net
4	Put the cut mesh into the hooking machine and hook it
5	Put the finished product on the turnover cart and put it in the finished product net placement area